

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0214/1

Work Order Type: Weatherization

Audit Name: 80008KN0214-AUDIT

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0214

Alt. Client ID: KNOX

AGENCY INFORMATION

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:		
Contractor's Signature:		

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Mobile Home built in 1975

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0214
Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0214/1

Report Run On: 5/8/2010

DOE Weatherization Assistant

Version 8.6.0 Page 1 of 8

Measures

	<i>Measure</i> 1 Mob	oile Home Belly Repair 6	360 sq ft		Componen	ts			Inspected
C	omment • Repair fastners	belly with a durable prod . Tape not allowed as a f	uct such a astner.	s Tyve	k. Secure w	ith mech	anical		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Mobile Home Belly Repair (+)	SqFt	660		*****			
2	Labor	labor	SqFt	660					
2	ther Detail								
			1	Measure	Sub Total:] 8	Sub Total:	
	Field Notes:					w			

	Measure			ove Old Torn Belly Insu GQ FT	ılation		Componen	ts			Inspected
C		of i	n a c	labor cost. Contractor to ertified land fill. Refer to A s and Southeast Field Gu	Appendix	old tor A- Sta	n belly insula ndards for W	tion and d eatheriza	dispose ation	Э	
							Estimated			Actual	
#	Material / I	Labo	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation			Remove Old Torn Belly Insulation	SqFt	660					
				Includes labor cost. Contractor to install using Resnet Grade 1 Standards. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor			Labor	SqFt	660					
C	Other Detail										
				100							
						Measur	e Sub Total:			Sub Total:	
	Fleid Notes	5:		100				,	V 1000 L		

Measure 3 DW	/H Pipe Insulation			Componen	ts			nspected
Comment				-				
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Pipe Insulation	Each	1					
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.			L.		3		
2 Labor	DWH Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:			·····					

	Measure 4 B	elly Fiberglass R-19 Batt			Componen	ts		,	nspected
Comment •Includes labor cost. Contractor's responsibility to seal penetration in floor before installing insulation. Contractor to install using Resnet Grade 1 Standards. Insulation is installed to maintain permanent contact with the subfloor above (paper side against subfloor) including necessary supports (e.g. staves for blankets). Insulation to have NO gaps, voids, or compressions. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.									
					Estimated		** ***********************************	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fbergls,R-19 Batt	SqFt	660				1	
2	Labor	Floor Insulation - Fbergls,R-19 Batt	SqFt	660					,
C	ther Detail								
L									;
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:		* to*** \(\frac{1}{2} \) ***********************************		* 1 10 1 1 to 5 to 6				

Actual	
Qty Unit Cost	Total
Taxaban and taxaba	
Sub Total:	
	Qty Unit Cost

Report Run On: 5/8/2010

Measur	e 6 Fix	Any Other Heating Syst	em Prob	lem	Compone	nts			Inspecte	
*Includes labor cost. Must be installed by a licensed mechanical contractor. Must perform an ACCA Manual J and submit with invoice. Must be equal to Amana or Goodman 13 Seer Split Heat Pump, 10 KW emergency heat. Size is approximately 1.5 ton. Final size will be determined by the Director of Housing. If size on ACCA Manual J is different from this write up, contact CAC before install. Includes complete duct system. Must perform an ACCA Manual D and submit with invoice. Must meet local codes. Liquid white Mastic to be applied to entire inside of boot to seal all seams. Top of boot where it meets subfloor to be caulked with appropriate caulk. Boots to be insulated on outside of boot to R-6. This is best performed with 2-part close cell foam. No changes allowed. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide. NOTE: When post audit is performed, all boots must be below 1 pascal with none over 3 pascals and not more than 3 boots over 1 pascal but less than 3 pascals. All duct to be insulated with a minimum of R6 insulation. No changes allow. Install thermostat. Must be equal to Honeywell's PRO 4000 Programmable										
	HIGHNO	stat. Must educate client	on operat	ion of	inermostat. <i>Estimat</i> ed	ſ		Actual		
# Material /	/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
¹ Health a	nd Safety	Replacement of Heating System	Each	1						
2 Labor		Labor	Each	1						
Other Detai	<u> </u>			_						

				Measur	Sub Total:		s	Sub Total:	***************************************	
Field Note	es:		T-1				***			

	Measure 7 Vap	or Barrier Needed 660 s	sq ft		Componen	ts			Inspected
C	walls an earth. M	6 mil poly. Must be insta d support piers. Must be lust be secured at all sea rization Materials and So	securely ms. Refer	fastene to Atta	ed. Must be achment A- S	cleated d	lown to	I	
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	660					
2	Labor	Labor	SqFt	660					
C	ther Detail								

						110 - 110 -			
			I	Measure	Sub Total:		S	Sub Total: [
	Field Notes:							L.	
			Work Ord	der Grar	nd Total:		Grand	l Total:	

Client ID: 80008KN0214 Alt. Client ID: KNOX

Work Order Name: WO/80008KN0214/1 Report Run On: 5/8/2010

Page 8 of 8